

ASSISTANT EXCUTIVE ENGINEER OFFICE, PUBLIC WORKS DEPARTMENT SUB DIVISION, KOLAR-563101 e-mail:aeepwdklr@gmail.com

No:AEE/PWD/Kolar/AE-2/structure stability/2025-26 73

Date: 29/4/2025

To,

The Principal, C.Muniswamy Public School,

Kumbarahalli (v), Tamaka (p), Kolar -563103

Sub: Issue Building structural Safety Certificate reg.

Ref: 1) Government Circular No.PWD.59/BED/2019 Bengaluru Date:07.05.2022

2) Your office letter No dated:27-03-2025

\*\*\*\*

With reference to the subject cited above, requesting for issuing Building Structural Safety Certificate for C.MUNISWAMY PUBLIC SCHOOL, Kumbarahalli Village, Tamaka post, Kolar taluk on verification, it is found that the Building has been constructed in the year 2014-15. The Building has been inspected on 02.04.2025.

In connection with this, the existing Building was tested and verified Physically on 02-04-2025.

The building is having Ground floor, First floor and Second Floor constructed by size stone masonry for foundation, R.C.C Columns, Brick masonry inside existing walls and R.C.C roof structure in the supervision of Sri. P.S. Chandrashekar, Engineer & Class-1 PWD Contractor.

The workmanship is good and structure is safe to run the school.

Yours faithfully,

Assistant Executive Engineer PWD Sub-Division, Kolar.