

KARNATAKA STATE FIRE AND EMERGENCY SERVICES



Office of the District Fire Officer, Kolar Fire Station, Tamaka Industrial Area Kolar-563 103. © 08152-243222.

No.28/FSR/DFO/KFS/2025

Date:05-06-2025

ANNEXURE-1

Group- B Educational Building

NBC-2016, Part-4, Table 7 (11) 3.1.3 Group B Educational Buildings Sub division B1 & B2. (These condition are indicative and not exclusive all relevant provisions related to fire and life safety of NBC 2016 are mandatory).

To, The Authorized Signatory M/s. C. Muniswamy Public School Sy. No.07, Kumabarahalli Village. Tamaka Post, Kolar Taluk, WEIRE AND Kolar District-563 101.

Sir,

Sub: Issue of 'Fire Safety Recommendation' for low rise educational building constructed & occupied at M/s. C. Muniswamy Public School situated at Sy. No.07, Kumabarahalli Village, Tamaka Post, Kolar Taluk, Kolar District-reg.

Ref: Your request letter dated 18-03-2025.

>>>*\@*<><

With reference to the subject cited above, the premises of M/s. C. Muniswamy Public School situated at Sy. No.07, Kumabarahalli Village, Tamaka Post, Kolar Taluk, Kolar District-563 101 was inspected by me on 02-04-2025 with respect to Fire prevention, Firefighting and Evacuation measures to be complied in the above premises and has submitted the details as under;

A. Details of the building / premises :-

0	1)	Name and Address of the	:	The Authorized Signatory	
	9 55°	Applicant.		M/s. C. Muniswamy Public School	
				Sy. No.07, Kumabarahalli Village,	
				Tamaka Post, Kolar Taluk,	
				Kolar District-563 101.	
	0.7			FIRE OF	

Page 1 of 6

02	Name and Address of the	T	M/ CM :
	premises.		: M/s. C. Muniswamy Public School
	promises.		Sy. No.07, Kumabarahalli Village,
			Tamaka Post, Kolar Taluk, Kolar District-563 101.
03) Name and address of the		
03	Building owner	:	The Authorized Signatory
	Dunuing Owner		M/s. C. Muniswamy Public School
			Sy. No.07, Kumabarahalli Village,
			Tamaka Post, Kolar Taluk, Kolar District-563 101.
04)	Number of 111		
04)	Number of buildings	:	One Building.
05)	Number of floors	:	Ground & 02 upper floors.
06)	Floor-wise details of occupancy:	_	
	Ground floor		07-Class rooms, Principle room, Office room,
			Staff room, Gents and Ladies Toilet rooms.
	1 st Floor	:	08-Class rooms, Staff room, Gents and
			Ladies Toilet rooms.
*	2 nd Floor	:	08-Class rooms, Staff room, Gents and
	3 47		Ladies Toilet rooms.
07)	Height of the building	:	10.90 mtrs.
08)	Site area	•	26,109.60 Sq. mtrs.
09)	Built-up area of each floor:-		OBSERVATION OF FREE PROPERTY OF FREE PRO
	Ground floor		1,090.00 Sq. mtrs.
	1 st Floor	:	1,090.00 Sq. mtrs.
	2 nd Floor	:	1,090.00 Sq. mtrs.
10)	Total built-up area	:	5,670.00 Sq. mtrs.
11)	Surrounding properties:-		
		:	06.00 mtrs. wide Chadhumanahalli road.
	West (Rear)	:	Private land.
	North (Side)	:	Private land.
	South (Side)	:	08.00 mtrs wide NH-75 service road.
12)	Open space all around the building	ng	<u>:-</u>
	E (E)		Min. 06.00 mtrs.
	W. (D)		
	west (real)	•	07.80 mtrs.

North (Side):	04.80 mtrs.	
South (Side):	03.10 mtrs.	

<u>B.</u> On inspection of this Educational premises, the following fire prevention, firefighting and evacuation measures recommended are considered absolutely essential from fire safety point of view:-

SI.				
No.	Details	Existi	Recommendations	
(1)	(02)	(03)	(04)	
01)	Accessibility to the	The Premises is a	The requirement is	
	premises	06.00 mtrs		Complied.
		Chadhumanahalli r		
		eastern side and 08		
		NH-75 service road		
		southern side and		
		hardened to carry 45,000 kgs.		
02)	No. of entrances	02 nos. of Entry/I	Exit have been	The requirement is
		provided.		Complied.
03)	Width of Entry/Exit	Each of Entrance/E	%	The requirement is
, o		width have been pro	ovided.	Complied.
04)	Diesel generators.	01 no. of 15 KVA		The requirement is
		been provided & C	And the second s	Complied.
e de ja		the staircase ligh		
		lightings and other		
05)	No. of Staircases	No. of Staircase:	02 No.	The requirement is
9	available	Width of :	Each of 01.50	Complied.
		staircase	mtrs	
8 72	***	Width of threads:	Each of 30	
2 9		II.:-1.4 - C.:	Cms	
II S		Height of risers :	Each of 15 Cms	
		No. of risers per :	Each of 12	
		flight	risers	
		Height of :	Each of 01.00	
		handrails	mtrs.	
		Head room :	Each of 03.00	
00	D4-1-1-	clearance	mtrs.	0 1 1
06) Portable > 08 nos. ABC type extinguis				Complied.
	extinguisher	each of 04 kgs		
		been provided.		
15		➤ One mechan	CYFIRE OFFE	

		and the second s	
		extinguisher of 9 ltrs. Capacity have been provided. ➤ 01 no. of CO ₂ extinguisher, 02 kgs capacity have been	
		provided.	
07)	Hose reel hose system	02 nos. of Hose Reel Hose near each staircase the hose reel hose of Minimum 19 mm size of adequate length to reach the farthest point of each floor have been provided. shut off branch having a nozzle of 5 mm size. The hose reel hose have been connected at each landing.	
08)	Terrace tank over respective tower terrace	The hose reel hose system have been connected to an overhead tank of 5,000 liters capacity exclusively for firefighting purpose.	
09)	At the terrace Tank Level with minimum pressure of 3.5 kg per cm ²	The hose reel hose system have been connected to a Booster pump capable of delivering 450 LPM capacity. Further the systems have been connected to an alternative source of power supply.	
10)	Escape routes	"Exits & Emergency Exit" Signage's written in bold letters marked in luminous paints have been indicated in the corridor/passage on each floor as a guide during evacuation near the staircases and near exits in each floor of this building.	
11)	Fire order (Fire Safety Plans)	A notice board have been indicating the action to be taken by the employees in case of an emergency with telephone number of Kolar Fire Station i.e. 08152-243222 and 101/112 telephone numbers of nearest Ambulance Services & Police station.	Complied.
12	1		Page 4 of 6

11	No smoking board.	COTPA Sec-4 direction No Smoking area smoking is an offence board have been provided and written in English & Kannada both languages have been prominently displayed at inside the entry/exit of the each floor.	Complied.
12	Fire Siren	A Fire Siren have been installed in the premises to inform the inmates in case of a fire emergency and evacuate the area.	Complied.
13	Nominate one Fire Nodal Officer	The school authority has been nominated Sri. Nishant has a fire nodal officer.	Complied.
14	Fire fighting training	Not imparted.	At-least 40% of Teaching and non Teaching staff should be got trained in basic fire prevention & Fire Fighting at the R.A Mundkur fire and Emergency Services Academy, B.G Road, Bengaluru.

15) General Fire precaution measures:

- A. Explosive and flammable materials should not be stored in the store room, UPS room, Electrical panel area, class rooms, laboratory & electrical sum panel premises.
- **B.** Accumulation of combustible waste in and around the premises should be avoided.
- C. The exit ways shall be always kept clear without any obstruction.
- D. Liquefied petroleum gas should be not stored in the building.
- E. The doors shall not be kept locked/latched during working hours and shall be free from obstruction.
- **F.** During the class hours the class room doors shall not be locked from inside to outside.
- G. As per Hon'ble Supreme Court order all teacher and staff shall be trained to handle safety equipment, initiate emergency evacuation and protect their students in the event of fire and other emergency and the school shall observe the Fire Safety day on April 14th of every year by conducting fire safety drills

age 5 of 6

with co-ordinate with Fire Service Department.

- **H.** This Fire Safety Recommendation is issued from the fire prevention, fire fighting and evacuation measures. Karnataka State Fire & Emergency Services Department is not responsible for the ownership of the land, its location and other disputes, which may arise in due course.
- I. If any additional construction work is taken up in the building/premises without informed to the department, the <u>"Fire Safety Recommendation"</u> deemed to be cancelled and necessary legal action will be initiated against the developer/management/tenant.

Under the above circumstance the Karnataka Fire & Emergency Service Department is issuing 'Fire Safety Recommendation' to M/s. C. Muniswamy Public School situated at Sy. No.07, Kumabarahalli Village, Tamaka Post, Kolar Taluk, Kolar District-563 101 subject to condition and compliance of the above recommendations in column-4 of part-B within 3 months and compliance to the undersigned.

This "Fire Safety Recommendation" is valid for Only One Year from the date of issue and it is renewable.

All requirements recommended above are as per National Building Code 2016 Part-4 clause 3.1.8 of Fire and Life safety will have to be complied with Mandatorily.

Yours faithfully

Ramataka State Fire & Emergency Services
Kolar Fire Station

Tamaka Industrial Area, Kolar - 563 103.